

Kyocera® F-3010/FBP-02 Toner Kit



Oasis Imaging Products, Inc. Technical Support: (888) 627-6555

Reference Information:

OEM PN: 403065-03

OEM Yield: 10,000/set

Approximate Remanufacturing

Time: 5 min.

Printer Compatibility Information:

CARLISLE SYSTL LASERGRAPH 18

DEREX INC DRL 20

IMAGE TECHNOLOGIES MPS-3010 MICR

KYOCERA F-3010A

KYOCERA FBP-11

LEXI 3012

LEXI 3019

LEXI 3019 II

LEXI 3087

LEXI 3087 II

ROSETTA RT 3010M MICR

STANDARD REGISTER PL 3000 MICR

Instructions:

1. Open the upper unit and remove the old waste toner bottle.
2. Cap the old bottle, put it in a plastic bag, and throw away.
3. Install the new waste toner bottle without the cap.
4. Remove the old fuser cleaning pad by the yellow tab.
5. Place the new fuser cleaning pad in the fuser, pad side down and yellow tab toward you. To prevent accidents, check that the new pad is positioned correctly and close the upper unit.
6. Insert new toner cartridge and pull seal.

Caution: The fuser unit and fuser cleaning pad may be hot. When you replace the toner cartridge, also replace the waste toner bottle and fuser cleaning pad.